Kowree Crescent, Sebastopol Fences covered with graffiti. Two recently planted, dead trees. Old plaground with low diversity and play value. Located centrally blocking flow. No tree planting. Bollards, no sense of entry. Isolated bench with no Opportunity for street trees. No overhead shade. Opportunity for planting of trees and greening. power lines. Post and rail fence.